

## 8.7 Spare Parts List

QTY PER UNIT	DESCRIPTION	RECOMMENDED SPARE QTY	DELTA F PART NUMBER
1	Electrolyte	2	EO-5
1	Battery Pack	1	16332530
1	Front Panel Board	1	10404820
1	Power Supply Board	1	10404890
1	Oxygen Sensor**	0	SP500
1	Fuse 0.25A SloBlo (110VAC)*	2	45002301
1	Fuse 0.125A SloBlo (220VAC)*	2	45002241
1	Fuse, Battery Pack, .5A	1	45002705
1	Power Cord (110 VAC)	0	59017237
1	Power Cord (220 VAC)	0	59036140
1	Cable Ass'y/Sensor Harness	0	13210470
1	Handle	0	65000004
2	Handle Screws	0	80103250
4	Feet	0	83005018
1	Calibration Cup	0	17205890
1	Panel Mount Kit	0	15305440

Table 9: Spare Parts List

**NOTE:**

\* The fuse required for a particular application is determined by the AC power input voltage.

\*\* When ordering a replacement sensor, please provide monitor model and serial number.

To order parts contact the Delta F Customer Support Services Department at 781-935-5808, Fax 781-932-0053, or e-mail at [service@delta-f.com](mailto:service@delta-f.com).